

■ Firmware Update

This manual is to explain the procedure for updating the AU-XP1 firmware on Macintosh.

■ Operating Environment

Please perform this update for AU-XP1 in the following environment.

- OS X 10.9 Mavericks
- OS X 10.10 Yosemite
- OS X 10.11 El Capitan

■ Preparation Before Updating

Before updating the AU-XP1 firmware, please make sure of the following points.

- Download AU-XP1 latest firmware update file "DVLH1002ZB.zip" for Macintosh from the website below and put it in any folder in your Mac.)

<http://pro-av.panasonic.net/en/> ->Service and Support ->Download -> P2


- If your Mac is connected with two or more AU-XP1 memory card drives, the update cannot be performed correctly. Be sure to perform the update with only one AU-XP1 drive connected.
- Disable the sleep setting of your Mac.
- If P2 cards are in the slots of AU-XP1, take them all out.
- AU-XP1 require the power supply with USB3.0 or AC Adaptor.

■ Firmware Update Procedure


* Update must be performed by a user with administrator rights.

1. Double-click the downloaded "DVLH1002ZB.zip" file to extract it and create the "DVLH1002ZB" folder.
2. Double-click the "Xpd1UpdateTo202_120.app" file in the "DVLH1002ZB" folder to start the update.

When AU-XPD1 is recognized correctly, following screen is displayed. Please proceed to the next step. (Version numbers below are for reference purposes only.)



If the screen is displayed as follows, AU-XPD1 is not recognized. Please check the connection with Mac again.



3. Click the [Execute] button to start the update.

It takes about a few minutes to complete the update.

* Once the update is started, it cannot be canceled in the middle of the process.

* While the update is in progress, please do not turn off your Mac or AU-XPDI, or unplug the USB cable.

* When the AU-XPDI indicates disconnection for a few seconds, this state proceeding normally.

It does not indicate problems.



4. When the update is completed, the following screen will be displayed as below.



5. With these steps, the update will be completed.

■ Confirmation of Firmware Version

When you need to confirm that AU-XPDP1 has been correctly updated, please execute the "Xpd1UpdateTo202_120.app" file again.

If it has been updated correctly, the following screen will be displayed.




If it has not been updated correctly, please perform the update from the beginning again.

■ Error While Updating

If an error occurs for some reason while updating, a message such as the following will be displayed in the window and the update process will be stopped.

- + Cannot communicate with AU-XPDP1. Ending process.
- + Error during version update, Ending process.
- + File transfer failed. Ending process.
- + File write failed. Ending process.

If the update is stopped, please follow the procedure below to perform the update again.

1. Press  button at the upper left of the window to terminate updating.
2. After turning your Mac off, turn AU-XPDP1 off and on again. Then restart your Mac.
3. Double-click the "Xpd1UpdateTo202_120.app" file to start the application.
4. After it is confirmed that AU-XPDP1 is recognized, press the Execute button to perform the update.

When the following symptoms occur, please contact your nearest service center.

- AU-XPDP1 is not recognized.
- The update is not completed correctly even if you have retried several times.